# Monthly Inspection NY/NJ

Performed at: Location #BP 123 Street - BP - 123 Street - fds, OH 44121 Submitted on: 01/17/2020 @ 06:44pm by Tech One

# **Spill Buckets**

Do the Gas fill and Vapor caps fit on the fill and drybreak properly and have a good gasket?

Yes

#### Is the fill pipe free from any obstructions (broken tank sticks)?

Yes

## Are there Overfill drop tubes present?

Yes

Are the Spill buckets and Vapor buckets (if applicable) free from having any rust, cracks or holes in the sides and bottom?

Yes

## Is the vapor recovery poppet rust free and seated well?

No



Taken on 01/17/2020 3:50 pm

## Is the spill bucket clean and free of any water, fuel and debris?

Yes



Taken on 01/17/2020 3:51 pm



Taken on 01/17/2020 3:51 pm



Taken on 01/17/2020 3:51 pm



Taken on 01/17/2020 3:51 pm



Taken on 01/17/2020 3:51 pm



Taken on 01/17/2020 3:51 pm

Are the fills and vapor clearly painted and correct configuration per API?

Yes

Is there an External Overfill Alarm?

No

# Tank Top of Transision Containment Sumps

## Is the containment sump free of any water, fuel and debris?

Yes





Taken on 01/17/2020 3:52 pm

Taken on 01/17/2020 3:52 pm



Taken on 01/17/2020 3:52 pm



Taken on 01/17/2020 3:52 pm

Is the containment sump free from having any cracks or holes in the sides and bottom?

Yes

## Is a sensor installed?

Yes

## Is the sensor positioned properly at the bottom of the containment sump to detect a leak?

Yes

## Are the Containment sump covers sitting properly and are the gaskets in place and in good condition?

Yes

## Are the PV vent Cap(s) visibly in good Condition?

Yes



Taken on 01/17/2020 3:52 pm

# **Dispenser Containment Sumps**

Are there Dispenser Sumps present?

Yes

## Is the containment sump free of any water, fuel and debris?

Yes







#### Taken on 01/17/2020 3:53 pm

Taken on 01/17/2020 3:53 pm

Taken on 01/17/2020 3:53 pm



Taken on 01/17/2020 3:53 pm



Taken on 01/17/2020 3:53 pm



Taken on 01/17/2020 3:53 pm

Taken on

01/17/2020 3:53 pm



Taken on 01/17/2020 3:53 pm



Taken on 01/17/2020 3:53 pm

## Is the containment sump free from having any cracks or holes in the sides and bottom?

Yes

Is a sensor installed?

Yes

Is the sensor positioned properly at the bottom of the containment sump to detect a leak?

Yes

Meters Or Piping Leaking?

No

## **Hanging Hardware**

Did any of the hanging hardware (Retractors,nozzles, whips, hoses, breakaways) have issues, such as wear or tear, upside down,or dirty with residue that should be repaired or replaced?

No

## (ATG) / Veederoot

## Is the ATG System turned on and functioning?

Yes

## Is the console free from any active alarms?

Yes

## Did you print out the required monthly Tank and Line leak test results?

Yes

Comment: Veeder root shows water in T4 Diesel, but the stick tank process shows no water present in



Taken on 01/17/2020 6:43 pm

## **Cathodic Protection**

#### Is there a Cathodic Protection Rectifier Present?

No

## **Site Information**

### Dispensers

10

## Stage II System

Non Vapor Recovery

## Was there a Complaince Notebook you had access to?

Yes

## Did you Check the Compliance Notebook for Expiring Paperwork Dates?

Yes

## Has or will anything Expire by the next month?

Yes

*Comment:* Weights and measures expired 1/31/19 Community Right to know will expire next month Missing Life Hazard, yearly compliance testing results and hydro testing results